Dino-Lite
Digital Microscope

DinoCapture 2.0
user guide

windows software

Dino-Lite Europe, 2010
www.dino-lite.eu

Introduction - About DinoCapture 2.0

The DinoCapture 2.0 software from AnMo Electronics Corporation is a free software program that is compatible and included only with products manufactured by AnMo Electronics Corporation. Based on customer feedback, we have included many new features that give users a superior experience with the Dino-Lite digital handheld microscopes.

With the DinoCapture 2.0 software you can add text, draw arrows, circles, and use other great drawing tools right on live video or on taken pictures and delete or edit the results if required. The DinoCapture 2.0 software also allows you to easily customize the drawing color and size giving you the proper look you want.

On certain models, the DinoCapture 2.0 offers a very powerful analysis tool which lets you measure on pictures as well as on live video. Measurements as well as text can be edited, reorganized, and deleted. The measurements can also be exported to Excel. For assured accuracy, you can also calibrate the measurements with some of our Dino-Lite models. The interface is organized and easy to use, allowing multiple user windows as well as the ability to use multiple Dino-Lite's on one computer!

The DinoCapture 2.0 software is a product created by AnMo Electronics Corporation dedication on providing a high quality, competitively priced, and versatile digital microscopy experience for professionals and casual users alike.

To get help on a topic, please find the appropriate chapter.

Menu Bar	Describes the buttons on the menu bar.	4
Image List Tools	Describes the buttons on the tool bar.	7
Preview Window Management Bar	Describes the features and functions of the preview window management bar.	9
Tool Bar	Describes the buttons on the tool bar.	10
Preview Window Tools	Describes the buttons on the preview window.	24
How to Steps	Gives step-by–step direction on common tasks.	26
Keyboard Controls	Describes powerful keyboard functions.	33
Mouse Controls	Describes powerful mouse functions.	34
Measurement Properties	Describes the measurement properties window.	35
Video Setting	Describes the video settings window.	38
Picture Setting	Describes the picture setting window.	40
Open Folder Window	Describes the open folder window.	42

Menu Bar

Folder

New

Displays the “New Folder” window that allows you to create a new folder to save pictures/videos. If no folders are created, the “New Folder” window will automatically pop up.
See Also: How to create a new folder

Open

Displays the “Select Folder” window, which allows you to open a previously created picture/video folder. You may also create a new folder.

Recent

Opens the previous saved folder. The DinoCapture 2.0 remembers the previously opened folder, so if you want to go back to the previous folder, select “Recent” and the image list reverts back to it.

Folder Properties

Displays the “Folder Property” window. Allows you to see the properties of the current folder and also allows changing the name and edit notes about the current save folder.

Exit DinoCapture

Exits DinoCapture 2.0 software.

Files

Open

Opens a selected picture or video to be viewed on the main view window.

Copy

Copies the selected picture or video to be pasted into another folder or program.

Save As

Opens the “Save as” window, which allows you to save the desired files into the required folder and file format.

Delete

Allows you to delete selected pictures or videos. You will be prompted to confirm your decision.
See also: Delete Key

Send Email

Allows you to send selected pictures through your default email account.

Slideshow

Starts a slideshow from the pictures in the Image List.

See Also:

How to start a slideshow

Show Image List

Slide Show

Print

Displays the “Print” window, which allows you to print the selected picture.

Close All Opened Files

Closes all open pictures or videos in the picture management bar.

Setting

Show Image List

Check for the image list to appear. Uncheck to hide the image list.

Show Tool Bar

Check to show the tool bar. Uncheck to hide the tool bar.

Show Status Bar

Check to show the status bar. Uncheck to hide the status bar.

Measurement Properties

The measurement properties selection allows reopening the measurement property window when closed. It will only be active when the preview window is in measurement mode.

Language

The language selection allows you to select the DinoCapture interface language.

Sound Effects

The sound effects give you audio feedback aiding in the use of the DinoCapture 2.0 software. The sound effects can be enabled and disabled with this checkbox.

Auto-Update

Toggles the DinoCapture 2.0 auto-update capabilities. With auto-update checked, the DinoCapture 2.0 software will automatically search the web for updates once the software starts.

Help

User's Guide

Opens the "User's Guide" that will help you to understand functions and features of the DinoCapture 2.0 software.

About DinoCapture 2.0

Opens the "About" page pop-up for DinoCapture 2.0. To exit click on the pop-up and the window will disappear.

License Agreement

Opens the license agreement PDF file

Image List Tools

Image List icons

Open

The open icon allows you to open a highlighted picture in the image list. Once an image thumbnail is selected, press the Open button to open the picture in the main window.

Copy

The copy icon allows you to copy a selected file and paste the image into a different location such as Microsoft Word.

Save As

Opens the "Save As" window so you can save the file or files into the desired file format or folder.

See Also:

Ctrl+A

Shift and Left Mouse Button

Ctrl and Left Mouse Button

Email

The Email icon allows you to email selected pictures without exiting the DinoCapture 2.0 software. Selecting the icon will open your default email client.

Print

The Print icon allows you to print the selected picture. This make it easy for users to save a printed copy of the image selected.

Slide Show

The Slide Show icon starts a slideshow of selected pictures in the Image List.

See Also:

How to start a slideshow

Show Image List

Slideshow

Delete

The Delete icon allows you to delete certain pictures from the image library. This is very useful to clean up the image thumbnail list of any unwanted pictures.

See Also:

Delete consecutive pictures

Delete multiple pictures

Delete key

Preview Window Management bar

Multiple Dino-Lite

The DinoCapture 2.0 software can use multiple Dino-Lite Digital Handheld Microscopes simultaneously. Simply select which camera to use by double clicking on the number located on the preview window management bar. Opened pictures and video will also be displayed on this bar.

See also:

Starting a live video feed

Closing a Window

On the preview window management bar located on the top of the main window, you can close an open picture by right clicking on the picture and select “Close window”.



See Also:

Ctrl and Left Mouse Button

Closing all Windows

On the preview window management bar located on the top of the main window, you can close an open picture by right clicking on the picture and select “Close all”.



Tool Bar

The tool bar is easily accessible under the preview window management bar and allows you to annotate images, do measurement and calibration (model specific), and it also allows you to edit the line and font settings.

Draw Tools



The draw tool set allows you to write text and draw on the images. The bar is located below the preview window management bar.

Text

The text tool lets you write text anywhere on the picture. Simply create the text box and then the area within the text box is ready to write in. To start a new text line, press ENTER. When done, left click out of the text box to finish.



Tip: You can edit the text by selecting the text icon and then clicking on the text you want to edit.

See also:

How to resize the text box

Line

The line tool allows you to draw lines on the picture. Simply click and drag to draw the desired line.



Arrow

The arrow tool allows you to draw arrows on the picture. Simply left click and drag your mouse to the place you want the arrow to point to.



Freelance

The freelance tool allows you to draw a line freely on the image. Simply left click the mouse once to start and click again to finish the drawing.



Rectangle

The rectangle tool allows you to draw rectangles on the image. Simple left click and drag out to create the size of the rectangle and click again to finish.



Oval

The oval tool allows draw ovals on the image. Simply left click to start the oval and click again to finish.



Measurement Tools



Notice: The measurement and calibration feature is only available for certain models. Please contact a local sales representative for further information.

Line Measurement

The line measurement allows you to measure the linear distance between two points. Simply left click and drag to the desired length, and click again to finish.



Continuous Line Measurement

The continuous line function allows measurement of the distance between multiple connecting lines. Simply click and drag to form one section of distance, click again to start another section. Continue until the total desired distance is measured. Double click to finish.



Polygon Measurement

The polygon measurement feature allows measurement of a polygon. Simply click and drag to form the desired length, and click again to start the next section. When finished, double click to finish the polygon measurement.



Radius of Circle Measurement

The radius of circle measurement allows you to measure the circumference, area, and radius of a circle. Simply click and extend out to the desired radius.



Diameter of Circle Measurement

The diameter of a circle measurement allows you to measure the circumference, area, and radius of a circle. Simply click and extend out to the desired diameter.



Three Point Circle Measurement

The three point circle measurement allows the measurement of the circumference, area, and radius of a circle. Simply click on any three points on the circle you wish to measure.



Three Point Arc Measurement

The three point arc measurement allows a measurement of an arc. Click on three consecutive points on an arc to measure.



Three Point Angle Measurement

The three point angle measurement allows the measurement of an angle. Start at the pivot point and extend out to start measuring an angle.



Four Points Angle Measurement

The four point angle measurement allows the measurement of an angle by selecting four points. Simply select two points from one line segment and another two points from another line segment to complete the angle measurement.



Text and Line edit



You can easily access line and text properties on the tool bar. The line and text can be customized to fit your needs.

Line Color

Press the Line Color Icon and the color list will expand for you to choose a line color.

Line Style

Allows you to select the style of the lines you create.

Line Width

Allows you to change the width of the lines you create.

Font

Clicking on the button opens the font window where you can change everything from size to color of the text represented on the images you write on.

Measurement properties window

Clicking on the icon allows you to show or hide the measurement properties window.



See Also: About the measurement property window

Notice: The measurement and calibration feature is only available for certain models. Please contact a local sales representative for further information.

Magnifier

Allows you to digitally enlarge the area around your mouse pointer for more details and accurate measurements.

Hint: Use the arrow keys on your keyboard for pixel by pixel movement.

Measurement Tools

If you have a Dino-Lite model capable of measurement or measurement and calibration, the magnification, units of measure and calibration will be available.

Magnification



Input the magnification in the blue box. The magnification can be read from the dial on the microscope. Once the image is in focus with the Dino-Lite, insert the magnification you see on the dial into the magnification box to start using the measurement tools.

See Also: How to measure

Units

The drop down box allows you to select the unit of measure.



inch- inches

mil- mil (1/1000 of an inch)

mm- millimeter

um- microns/micrometers (1/1000 of a millimeter)

Calibration menu

No calibration: Use the default measurement settings.

New Profile: Create a new calibration profile.

Open Calibration Folder: Opens the folder where your calibration settings are located. From that window you can select already created calibration profiles or delete them.

See Also: How to calibrate measurements

Notice: The calibration feature is only available for certain models. Please contact a local sales representative for further information.

Preview Window Tools

MicroTouch

The MicroTouch tool is activated when you touch the MicroTouch trigger after starting the DinoCapture 2.0 software. After the software recognized that the Dino-Lite has the MicroTouch feature, you can activate or deactivate the MicroTouch controls with this button.
The MicroTouch was designed to minimize image blur while taking a picture with the microscope. Great for those moments when you need to take a picture, but having a hard time reaching the computer.
Notice: Not all models include the MicroTouch feature. Please check your local sales representative for more details.

LED Control

Allows you to control the LED's. Lets you turn ON/OFF or switch LED's on the Dino-Lite.
Notice: The AM211 and AM2011 do not have LED control

Setting

The Setting icon allows you to open the Setting window. The setting window allows you to control the camera settings.

Full Screen

The "Full Screen" icon lets you see the live video or picture in full screen. To exit full screen mode, click anywhere on the screen.

Close Window

The "Close Window" icon allows you to close the current window. If too many windows are open or you just don't need to see the current picture anymore, you can simply press the "Close Window" icon and it will be removed from the main screen.

Calibration

The "Calibration" menu only appears on models that support measurement and calibration capabilities. The calibration feature for the DinoCapture 2.0 has the ability to create multiple calibrations for a single Dino-Lite by putting the calibrations into a calibration profile. If multiple Dino-Lite's are owned, another profile can be created.
The DinoCapture 2.0 calibration feature gives the convenience of not needing to recalibrate for each magnification needed or different models owned.
See Also: How to calibrate measurements

Magnification Mag. :

For models that have measurement capabilities, the magnification box is where you see the magnification that is being used for the measurement

Unit Unit:

Shows what unit of measure is selected for the active child window.

Resolution 1280x1024

There are multiple resolutions you can set the Dino-Lite to. Certain models have a maximum resolution of 1280x1024 giving very clear images at any magnification.

Annotation

You can write annotations on the bottom of the preview window. Click on the gray bar on the bottom of the preview window and the annotation box will expand. Write text within this box and press ENTER to start a new row. When done, left click anywhere in the preview window to save the annotation and exit the annotation box.

How to Steps

How to measure

1. Input magnification that is read from the microscope into the magnification box.

Magnification value on Dino-Lite



2. Select a measurement tool.



3. Select a unit of measure.



4. For example: to measure distance.

5. Left click your mouse once to start the measurement.
6. Left click your mouse once more to end the measurement.

Hint: For more accurate measurements, click on the magnify icon . While using the magnify feature, use the arrow keys on your keyboard for pixel per pixel movement. When set to a desired location, click the left mouse button or press “Enter” on the keyboard to set the desired endpoint.

See also: Using the magnifier

How to calibrate measurements

1. In the live video window select the Calibration drop down menu (or click on the calibration button).
2. Select “New Profile”.

3. A small window will pop up. Give the profile a name and any necessary information.



4. Click “Continue Calibration” when done naming the profile.
5. In the new menu, Press “F8” or use the “Freeze” button to freeze the calibration object.



6. Enter the magnification that can be read from the Dino-Lite. Press Enter when finished.
7. A red bar with two blue dots will appear with pink guidance lines, you are now ready to calibrate.

8. Click on one of the blue dots to start moving the blue dot to your desired location.
9. Click again to stop.
10. Click on the other blue dot to start setting the other end point.
11. Click the left mouse button again to stop.
12. When the correct distance is measured, enter the known distance.
13. Enter the unit of measure by selecting the “Unit” dropdown box.

14. Press “Finish” when done.

Hint: You can create multiple calibration profiles for different Dino-Lite models.

How to adjust measurements and drawings

1. When no tools are selected move your mouse over to the measurement you want to adjust. The mouse pointer will become a pointing finger .
2. When the mouse becomes a pointing finger over a line or result, click on it once.
3. Now move your mouse over an endpoint. It will be accentuated with a blue square at adjustable points. The cursor will change to a moving cursor to notify that you can select and move the endpoint.
4. Click on the adjustable and move the end point to the desired location.
5. Click again to set the new endpoint.

How to move the text box and measurement results to a different location

1. When no tools are selected move your mouse over the text box, measurement, or drawing that you want to move. The mouse pointer will become a pointing finger .
2. When the pointer becomes a pointing finger ,click on the item you want to move to select it.
3. Once selected, the pointer will become an open hand when it is over a movable object.
4. When the pointer is an open hand , left click, and the hand will grab indicating that the item is now movable.
5. Move the text or measurement results with the mouse to the required location.
6. Left click again to set the text or measurement results onto its new location.

Hint: When an item is selected, you can delete it by pressing the “Delete” key on the keyboard.

How to move only the measurement text

1. When no tools are selected move your mouse over the text box, measurement, or drawing that you want to move. The mouse pointer will become a pointing finger .

2. When the pointer becomes a pointing finger , click on the item you want to move to select it.
3. Move your mouse over a measurement result text. The mouse will become an open hand allowing for selection.
4. Left click on the measurement result once to release it from its current location.
5. Left click again to set it to its new location.

See also: How to move the text box and measurement results to a different location

Using the magnifier

Click on the magnifier to open a window with a digitally zoomed image. You can move the mouse pointer pixel by pixel by using the arrow keys on the keyboard. Left click, or press "Enter" to set an endpoint if using a measurement or draw tool.

Deleting a measurement

1. On the measurement properties window select the measurement you want to delete.
2. Select Delete.

See Also:

Deleting consecutive pictures

Deleting multiple pictures

Delete Key

Deleting consecutive pictures

To delete multiple pictures in a row, hold down the SHIFT key and highlight the pictures you want to delete. Press the trash button to delete. You will be prompted to confirm.

Deleting multiple pictures

To delete certain pictures at the same time hold down the CTRL key while selecting the pictures you wish to delete. Press the trash button to delete. You will be prompted to confirm.

Hint: Ctrl+A selects all pictures on the image list.

Recording a video

1. In the active live video window, click on the icon to start a video.
2. A red record dot will start flashing when recording .
3. Click the video record button again to stop recording.
4. Select the "Video" tab to check the recorded video.

How to create a new folder

1. Click the “Folder” icon on the top left corner of the main window.
2. Select “New” to open the New Folder pop up window.



3. In the “New Folder” window give the new file a name by filling in the text box next to “Name”.
4. Press the Directory button and choose the directory you would like the new picture and video folder to be located.
5. When finished selecting the directory, press “OK” and the new folder is ready to use.

Note:

- If no folders are selected. The “New Folder” window will pop up for you to create one.
- If no Directory is selected, DinoCapture 2.0 will create a Digital Microscope folder in “Documents” or “My Documents” folder.

Full Screen

1. Press to preview in full screen.
2. Click anywhere on the screen to exit full screen.

How to Draw

1. Click on a draw tool on the tool bar.



2. For example we will draw a line.

3. Click the left mouse button to start the line.
4. Click the left mouse button again to stop the line.

How to add text

1. Select the Text tool to start adding text.
2. First create the window size for the text to be put in.
3. Once the box is drawn, you are ready to enter text in the text box.
4. Click outside the text box to stop.

Hint: Press ENTER to start a new line.

See Also:

How to adjust measurements and drawings

How to move the text box and measurement results to a different location

How to start a slideshow

1. Highlight the pictures you want to see in a slideshow with ctrl+ left mouse button.
2. After the desired pictures are selected, press the slideshow button .
3. Left-click to see the next picture or press “Esc” on the keyboard to cancel.

See Also: Slide Show

How to move the preview windows

1. When the mouse pointer turns into the move icon hold the left mouse button.
2. While the left mouse button is pressed, drag the window to your desired location.
3. Release the left mouse button to set the window in its new location.

Note: The preview windows stack on top of each other when opened. The amount of preview windows opened will be displayed on the Preview Window Management Bar.

How to clear drawings

1. Right click on an active window when the cursor is in move window mode .
2. A menu will pop up. Select clear.

3. You can select to clear all drawing, measurements, or both at the same time.



See also:

Deleting a measurement

Clear all measurements and drawing

Delete Key

Hint: To delete one drawing or measurement, select it and press “Delete” on the keyboard.

How to resize the text box

1. When no tools are selected, mouse over to the text that you want to resize. The mouse pointer will become the move object pointer .
2. Left click and the pointer will become an open hand .
3. Move the mouse to the blue square and the mouse will turn into . Left click the mouse and the text box will be resizable.
4. Left click again to set the new location.

How to create parallel and horizontal lines

Hold down the “Shift” key on the keyboard while drawing a line, this allows you to easily create vertical or horizontal lines by allowing the line to move only 90 degrees.

Keyboard Controls

Keyboard Controls

Keyboard controls provide more ease and practicality with the DinoCapture 2.0 experience.

Delete key

You can delete pictures on the image list simply by pressing the “Delete” key.

You can also delete selected or active annotations and measurements with the “Delete” key.

F7 Key

Pressing the F7 on the keyboard opens the time-lapse window.

F8 Key

Pressing F8 on the keyboard can freeze a live video feed from the Dino-Lite.

F9 Key

Pressing F9 takes a simultaneous snapshot with all live Dino-Lite’s.

F10 Key

Pressing the F10 on the keyboard enters full screen mode. Press F10 again to exit.

F11 Key

Pressing the F11 on the keyboard takes a snapshot of the specimen in the active video window.

F12 Key

Pressing the F12 key on the keyboard lets you start recording a video. Pressing the F12 key again stops the recording.

Ctrl+A

Pressing Ctrl+A selects all files on the image list.

Ctrl+Z

Undo last drawing or measurement.

Esc

Abort using tools.

Shift and Left Mouse Button

Holding the Shift key and clicking on the first and last images desired; highlights the group of images.

See Also: Deleting consecutive pictures

Ctrl and Left Mouse Button

Highlight desired pictures by holding the Ctrl key and select desired pictures or video by pressing the left mouse button.

See Also: Deleting multiple pictures

Arrow keys

With the magnifier active, use the arrow keys to move the cursor pixel by pixel for precision movement.

See Also: Magnifier

Mouse Controls

Opening a picture

To open a picture, you can simply DOUBLE click its thumbnail.

Moving a window

When you hold down the left mouse button on a child window, you can drag the window anywhere within the main window.

Stopping continuous line and polygon measurements

DOUBLE left clicking stops the continuous line and polygon measurements.

Starting a live video feed

Double clicking the camera icon on the preview window management bar starts a live video feed. For example if one Dino-Lite is plugged in, double click the thumbnail and the live video will start.

See also: Preview Window Management Bar

Taking a picture

You can also DOUBLE left click to take a picture in the live video window, or use the picture button.

Measurement Properties

About the measurement property window

The measurement property window organizes and shows the status of all the measurements as well as the ability to adjust how the results are shown on the image.



The Tabs

The DinoCapture 2.0 software separates each type of measurements into tabs helping you to organize your measurements.

Line

The Line tab shows all the properties of the line measurements as well as the ability to select what information is shown on the image, ability to delete, change units of measurement, and also export data to excel.

Polygon

The Polygon tab shows all the properties of the polygon measurements as well as the ability to select what information is shown on the image, ability to delete, change units of measurement, and also export data to excel.

Circle

The Circle tab shows all the properties of the circle measurements as well as the ability to select what information is shown on the image, ability to delete, change units of measurement, and also export data to excel.

Arc

The Arc tab shows all the properties of the arc measurements as well as the ability to select what information is shown on the image, ability to delete, change units of measurement, and also export data to excel.

Angle

The Angle tab shows all the properties of the angle measurements as well as the ability to select what information is shown on the image, ability to delete, change units of measurement, and also export data to excel.

Categories

Show

The show checkbox let you see the measurement results for the selected measurement on the image. Deselecting the checkbox hides the selected measurement results.

Name

Displays the name of the measurement.

Length

Displays the length of the measurement (L).

Area

Displays the area of the measurement (A).

Radius

Displays the radius of the measurement (**r**).

Angle (deg)

Displays the angle of the measurement ($\angle$).

Color

Displays the selected color of the measurement.

Line Width

Displays the width of the measurement lines.

Display

The display check boxes control what you would be able to see on the picture. Only the values that are relevant to the type of measurement are available for selection, others are greyed out. Un-checking and checking the boxes controls all measurements of the same type.

Name

Display the name of the measurement.

Length

Display the length of a measurement.

Area

Display the area of a measurement.

Radius

Display the radius of a measurement.

Angle

Display the angle of a measurement.

Buttons

Delete

Select a measurement and click on “Delete” to remove the measurement.

Clear all measurements and drawing

Clear all measurements and drawings on the active window.

Export to excel



Exports the data on the active window to Excel.

Close

The “X” on the top right corner closes the measurement properties window. Go to settings and select “Measurement Properties” to reopen the window.

Video setting

About video setting

The video settings can only be activated on the video preview window. Once video settings is activated, you can adjust many camera controls. While the video settings window is activated, all other functions in the DinoCapture 2.0 software cannot be used. Press “OK” or “Apply” to restore DinoCapture to its normal state.

To open the video setting window, press the setting button when the active window is a live video feed from a Dino-Lite.

Adjust Camera Properties Window



Microtouch controls

The MicroTouch (touch sensitive static sensor) feature on the handheld digital microscope gives users the option of taking a picture right from the microscope itself. The MicroTouch was designed to minimize image blur while taking a picture with the microscope. Great for those moments when you need to take a picture, but have a hard time reaching the computer.
Notice: Not all models have the MicroTouch feature. Please contact a local salles representative for more information.

Picture setting

About the picture setting page

The picture setting page allows you to change the pictures colors and quality. When the picture setting window is open, all other functions of the DinoCapture 2.0 software are disabled. Press “Close” to restore DinoCapture 2.0 to its normal state.

To open the picture setting window, press the setting button when the active window is a picture.

Color

Lets you adjust the color properties of the selected picture.

Contrast

You can adjust the contrast of the picture.

Brightness

You can adjust the brightness of the picture.

Saturation

You can adjust the saturation of the picture.

Hue

You can adjust the hue of the picture.

Gamma

You can adjust the gamma of the picture.

Sharpness

Allows you to adjust the sharpness of the selected picture.

Range

You can change the range of the sharpness.

Strength

You can adjust the strength of the pixel.

Picture Setting Buttons

Default

Resets the picture settings back to default.

Close

Closes the picture setting window and allows the use of the rest of the DinoCapture 2.0 program.

Open Folder window

Open Folder

You may select previously created folders in the Open Folder window. Press OK to confirm the folder you wish to use. You may also add previous folders or create a new folder.



Note: If you deleted a folder, you would need to add it to the list again by clicking the “Add Previous Folder” button.

See also:

Add Previous Folder

How to create a new folder

Add Previous Folder

Allows you to add a previously created folder into the folder list; simply select the folder you created for the DinoCapture 2.0 that contains the Picture and Video and press OK.

Create Folder

The create folder button opens the New Folder window for you to create a new folder for the DinoCapture 2.0 software to store images and video.

See also:

How to create a new folder

DinoCapture End User License Agreement

By using this software("DinoCapture Software") you agree to accept a license under and be bound by the following terms and conditions (the "Agreement").

Non-Commercial Use Only

DinoCapture Software is made available to you for your non-commercial use only. This means that you may use it at work or at home in conjunction with any product manufactured by AnMo Electronics Corporation (the “AnMo”). But you first need to obtain permission from AnMo if you want to sell the DinoCapture Software or any information, services, or software associated with or derived from it, or if you want to modify, copy (except as provided below), license, or create derivative works from the DinoCapture Software, if you are not using the Software in conjunction with AnMo’s product. This Agreement allows you to install and use the DinoCapture Software for working with Dino or Dino-Lite Digital Microscope, or the DinoEye digital eyepiece for microscope, or any other product manufactured by AnMo. You may make copies of the DinoCapture Software and distribute such copies to others within your employer organization provided that any such recipient has had an opportunity to review and agree to be bound by this Agreement. If others within your organization do not have this opportunity to review and agree and you would still like to distribute copies to them, you may do so provided that you have the legal right to bind your organization (and others within your organization) to this Agreement. If you do not have this right and the recipients do not have an opportunity to review and agree to this Agreement, please do not distribute the DinoCapture Software to them. If you have any questions regarding the terms of distribution, please send an email to support@anmo.com.tw . For each copy of the DinoCapture Software authorized under this license, you may make one backup copy, provided your backup copy is not installed or used concurrently on different computers. You must reproduce on any such copy all copyright notices and any other proprietary legends on the original copy of the DinoCapture Software. AnMo is not obligated to provide maintenance, support, or updates to you for the DinoCapture Software. If you have comments on DinoCapture Software or ideas on how to improve it, please email support@anmo.com.tw . Please note that by doing so, you also grant AnMo and third parties permission to use and incorporate your ideas or comments into the DinoCapture Software (or third party software) without further compensation.

Automatic Updates

The DinoCapture Software may communicate with AnMo's servers to check for available updates to the DinoCapture Software, such as bug fixes, patches, enhanced functions, missing plug-ins and new versions (collectively, "Updates"). The DinoCapture Software sends AnMo a request for the latest DinoCapture Software version information. If a newer version is available, the DinoCapture Software will give you the option of downloading it. The DinoCapture Software asks for permission before downloading an updated version. By installing the DinoCapture Software, you hereby agree to automatically request and receive updates from AnMo's servers.

Intellectual Property

You acknowledge that AnMo owns all right, title and interest in and to the DinoCapture Software,

portions thereof, or software or other materials (not including user photos or message text) provided through or in conjunction with the DinoCapture Software, including without limitation all intellectual property rights. You agree not to modify, adapt, translate, prepare derivative works from, decompile, reverse engineer, disassemble or otherwise attempt to derive source code from DinoCapture Software. You also agree to not remove, obscure, or alter AnMo's or any third party's copyright notice, trademarks, or other proprietary rights notices affixed to or contained within or accessed in conjunction with or through the DinoCapture Software.

Disclaimer of Warranties

AnMo and its licensors and suppliers disclaim any responsibility for any harm resulting from your use of the DinoCapture Software and/or any third party software accessed in conjunction with or through the DinoCapture Software.

THE DINOCAPTURE SOFTWARE AND ANY THIRD PARTY SOFTWARE MADE AVAILABLE IN CONJUNCTION WITH OR THROUGH THE DINOCAPTURE SOFTWARE ARE PROVIDED "AS IS," WITH NO WARRANTIES WHATSOEVER. ANMO AND ITS LICENSORS AND SUPPLIERS EXPRESSLY DISCLAIM TO THE FULLEST EXTENT PERMITTED BY LAW ALL EXPRESS, IMPLIED, AND STATUTORY WARRANTIES, INCLUDING, WITHOUT LIMITATION, THE WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, AND NON-INFRINGEMENT OF PROPRIETARY RIGHTS. ANMO AND ITS LICENSORS AND SUPPLIERS DISCLAIM ANY WARRANTIES REGARDING THE SECURITY, RELIABILITY, TIMELINESS, AND PERFORMANCE OF DINOCAPTURE SOFTWARE AND SUCH THIRD PARTY SOFTWARE. YOU UNDERSTAND AND AGREE THAT YOU DOWNLOAD AND/OR USE THE DINOCAPTURE SOFTWARE AND ALL THIRD PARTY SOFTWARE MADE AVAILABLE IN CONJUNCTION WITH OR THROUGH THE DINOCAPTURE SOFTWARE AT YOUR OWN DISCRETION AND RISK AND THAT YOU WILL BE SOLELY RESPONSIBLE FOR ANY DAMAGES TO YOUR COMPUTER SYSTEM OR LOSS OF DATA THAT RESULTS FROM THE DOWNLOAD OR USE OF DINOCAPTURE SOFTWARE AND SUCH THIRD PARTY SOFTWARE.

Limitation of Liability

UNDER NO CIRCUMSTANCES SHALL ANMO OR ITS LICENSORS AND SUPPLIERS BE LIABLE TO ANY USER ON ACCOUNT OF THAT USER'S USE OR MISUSE OF THE DINOCAPTURE SOFTWARE. SUCH LIMITATION OF LIABILITY SHALL APPLY TO PREVENT RECOVERY OF DIRECT, INDIRECT, INCIDENTAL, CONSEQUENTIAL, SPECIAL, EXEMPLARY, AND PUNITIVE DAMAGES WHETHER SUCH CLAIM IS BASED ON WARRANTY, CONTRACT, TORT (INCLUDING NEGLIGENCE), OR OTHERWISE. SUCH LIMITATION OF LIABILITY SHALL APPLY WHETHER THE DAMAGES ARISE FROM USE OR MISUSE OF AND RELIANCE ON THE DINOCAPTURE SOFTWARE, FROM INABILITY TO USE DINOCAPTURE SOFTWARE OR FROM THE INTERRUPTION, SUSPENSION, OR TERMINATION OF DINOCAPTURE SOFTWARE (INCLUDING SUCH DAMAGES INCURRED BY THIRD PARTIES). SUCH LIMITATION SHALL APPLY NOTWITHSTANDING A FAILURE OF ESSENTIAL PURPOSE OF ANY LIMITED REMEDY AND TO THE FULLEST EXTENT PERMITTED BY LAW. SOME STATES OR OTHER JURISDICTIONS DO NOT ALLOW THE EXCLUSION OR LIMITATION OF LIABILITY FOR INCIDENTAL OR CONSEQUENTIAL DAMAGES, SO THE ABOVE LIMITATIONS AND EXCLUSIONS MAY NOT APPLY TO YOU.

Indemnification

It is your responsibility to ascertain whether any copyright or other licenses for use of content are

necessary and to obtain any such licenses. You agree to copy, distribute, display, and modify only those materials which you have the necessary permission to use. You agree to hold harmless and indemnify AnMo and its subsidiaries, affiliates, officers, agents, and employees from and against any third party claim arising from or in any way related to your use of the DinoCapture Software, including any liability or expense arising from all claims, losses, damages (actual and consequential), suits, judgments, litigation costs and attorneys' fees, of every kind and nature. In such a case, AnMo will provide you with written notice of such claim, suit or action.

Miscellaneous Provisions

This Agreement will be governed by and construed in accordance with the laws of the Republic of China, without giving effect to the conflict of laws provisions of Republic of China or your actual country of residence. If for any reason a court of competent jurisdiction finds any provision or portion of this Agreement to be unenforceable, the remainder of this Agreement will continue in full force and effect. This Agreement constitutes the entire agreement between the parties with respect to the subject matter hereof and supersedes and replaces all prior or contemporaneous understandings or agreements, written or oral, regarding such subject matter. Any waiver of any provision of this Agreement will be effective only if in writing and signed by AnMo.

Termination

IF YOU WISH TO TERMINATE THIS AGREEMENT, YOU MAY SIMPLY CEASE USING THE DINOCAPTURE SOFTWARE AND FOLLOW THE UNINSTALL INSTRUCTIONS. ANMO RESERVES THE RIGHT TO TERMINATE THIS AGREEMENT AND YOUR AUTHORIZATION TO USE THE DINOCAPTURE SOFTWARE AT ANY TIME WITHOUT CAUSE.

Warranty

The DinoCapture software is provided for use with a Dino-Lite digital microscope supplied by AnMo Electronics or one of its distributors or resellers. The use of the DinoCapture software is guided by the End User License Agreement.
The Dino-Lite product is delivered with a two year warranty from the date of purchase by the end customer. Please note that accessories (i.e. detachable caps/extensions) are not covered under warranty. For warranty issues please contact the reseller or store where you bought the product.

Support

If you have any problem or issue with your Dino-Lite or the DinoCapture software, please check the Dino-Lite Europe support pages at www.dino-lite.eu.

IDCP/Dino-Lite Europe
Rijksweg 81-J
1411 GE Naarden
Tel. +31 20 6186322
Fax. +31 20 6189692
e-mail: info@idcp.nl
web: www.dino-lite.eu

© AnMo/IDCP/Dino-Lite Europe.
No part of this publication may be reproduced or distributed unless for personal use in conjunction with usage of Dino-Lite digital microscopes.

Dino-Lite
Digital Microscope

Patent info:

US Pat. No. 7.102.817.B1
Germany Pat. No. 20 2006 001 409.8
Japan Pat. No. 3123176
Taiwan Pat. No. M302031
Taiwan Pat. No. D118565
China Pat. No. ZL 2006 2 0139 073 X
China Pat. No. ZL 2006 3 0147 034 X

Dino-Lite Europe, 2010
www.dino-lite.eu